			erification Form fund Eligibility Deter	mination				
(1) Site Name	Dynagen, Inc.; General Tire and Rubber Company; Ameripol Synpol Corp Odessa Plant		(2) Prepared By:	Anna Lu	nd	(3) Date:	2/14/20	<u></u> 11
(include all a.k.a.s):			(4) Team Leader Approval:	Melissa	Corde	ll Q	25/11	
(5) Site Type: State or Federal	State 🔻		(6) SDA ID	. N/A	(7) CA	rs id	N/A	
(8) EPA ID	TXD057422685		(9) RN#	101871507	(10) IHV	(10) IHWCA/SWR 302		;
(11) Other ID	N/A		(12) Latitude:	31.825000				
(13) Address of Site:	2000 E Pool Road; Between S. Grandview Road & Dixie Blvd.		(14) Longitude:	-102.337500				
			(15) GPS Location:	SITE CENTER \blacksquare				~
(16) City:	Odessa		(17) Method of GPS Collection:	MAP INTERPOLATION-DIGITAL			•	
(18) Type of Operation:	Manufacturer of Synthetic Rubber		r (19) TCEQ Region:	7	(20) County ECTOR			▼.
(21) Dates of Operation:	1957 - 2002		(22) Hazardous Substances:	Benzene; Styrene; Xylene; Xylol; Acetone; Methanol; Toluene; Trichloroethane; Asbest Popcorn Polymer; Ion Exchange Resin; Naph Incinerator Ash; Dried Biological Sludge				
(23) Pathways:			▼		—			•
(24) Groundwater Contamination?	Unknown	_	(25) Aquifer:	(26) TWC No 26.408:		No	V	
(27) Referral Source:	EPA		(28) Referral Date (mm/dd/year):			4/20/1989		
(29) Activity Type:	VER (30) If the activity is complete, include the date of completion:					010		
			ctivity Type Codes:					
			State HRS complete	PA-C = Preliminary Assessment complete			te	
			iate removal complete SI-C = Site Inspection complete eCERCLIS complete ESI-C = Expanded Site Inspection complete				loto	
SSE-C = State Sampling/Eligibility complete P-CER-C = SS-C = State Screening complete NONSTD-C			Non-Standard complete FHRS-C = Federal HRS complete			iete		
(31) State Superfund Site Eligibility Status Determination:								
Determine the approp	riate eligibility categor					the drop d	own list	<u> </u>
betermine the approp	Choose from the list	- প্রতী মার্চান টার্চা রকারীব িশা ক	NFA NFA	▼				
Currently on State Superfund Registry (SSF) or National Priorities List (NPL) 643288								
Site under Evaluation	in the PA/SI program	- not eligible	for State Superfund	(PASI EVAL)	-			
Active/inactive facility	- currently in Other (OTH) progra	am or agency or shoul	ld be submitted to	OTH pro	gram or ag	gency	
(ex. OCE, VCP,	IHWCA, etc.) Submit	to Office of C	Compliance and Enfo	rcement (OCE) for	r addition	al enforcen	nent activi	ties
Agency and Program:				Program				
	gible for State Superfu	nd (A).					-	
	fficient data for evalua		s, sampling needed (S	N) or site visit nee	ded (SV)			
Non-site based on TC	EQ/EPA investigation (NS).						
No Further Action at	this time under State S	uperfund ba	sed on TCEQ/EPA in	vestigation (NFA)	•, ,			1. s
Date of	NFA determination:			11/15/	2010			
Eligible inactive facilit	ty - prioritize for imme	diate remova	al determination and s	state screening and	i HRS pa	ckage prep	aration (El	Ĺ).
	(32) Site Si	ummary begins on	Page 2.				

Dynagen Inc., also known as Ameripol Synpol Corp Odessa Plant and General Tire and Rubber Company, is located at 2000 E Pool Road in Odessa, Texas. The Site is an inactive synthetic rubber manufacturer which was in operation from 1957-2002 and covered over 300 acres.

Dynagen Inc. manufactured synthetic rubber since 1975. The facility utilized an onsite incinerator for the disposal of styrene resin polymer, xylene, and xylol. Additional areas of concern were six solar evaporation ponds which received cooling tower blow-down and had liners that were damaged. Several organic solvents were utilized throughout the years, primarily for cleaning purposes. These chemicals included: acetone, xylene, xylol, methanol, toluene, trichloroethane, and tetrachloroethane. Other hazardous materials of concern listed in the PA were: asbestos, popcorn polymer, ion exchange resin, naphtha, incinerator ash, and dried biological sludge.

As of April 15, 1986, the Texas Water Commission certified that the drum storage area, incinerator, and popcorn polymer waste pile closed as hazardous waste facilities in accordance with the approved closure plans under Dynagen, Inc.

On January 1, 1990, the Superfund Site Strategy Recommendation (SSSR) recommended a medium priority Site Inspection (SI) due to the presence of an incinerator used onsite for the disposal of styrene resin polymer, xylene, and xylol. Additional areas of concern at the Dynagen Inc. Site, were six solar evaporation ponds which received cooling tower blow-down and had liners that were damaged. On March 18, 1996 another SSSR was conducted and described this site as a candidate to be tasked for a SI.

According to the Industrial and Hazardous Waste Corrective Action's (IHWCA) facility log, Dynagen Inc., received a "complete" status for this project on November 22, 2002 under the following program identification #: 30252. The complete status for this project includes the incinerator (referred to as unit project 3911) and six solar evaporation ponds.

A phone call was made on November 15, 2010 to the Ector County Appraisal District (CAD). Lesley Wright from the CAD said the facility has been closed since 2002; however, the land is still currently owned by Dynagen Inc. According to data obtained from the Texas Water Development Board as of November 15, 2010, there are three domestic wells used within a one mile radius of the given GPS coordinates.

Based on IHWCA's facility log indicating a "complete" status on November 22, 2002 for the incinerator and six solar evaporation ponds, as of November 15, 2010 no further action is recommended for this site under the State Superfund program at this time.

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY TELEPHONE MEMO TO THE FILE

riease complete with typewriter of black pent.	•
1. 2 /2.	
call to: Ameripal Sympol	Call from: <u>Annal und</u>
Date of call: NOV. 15,2010	File no.: \$\frac{\text{N/O 87/5 07 7XD 057 4224}}{\text{Tile no.: }\frac{\text{N/O 87/5 07 7XD 057 4224}}{\text{Tile no.: }\frac{\text{N/O 87/5 07 7XD 057 4224}}{\text{Tile no.: }\text{N/O 87/5 07 7XD 057 4224}}
Phone no.: (201) 474-1923	subject: Dynagen; Ameripal Sympol
Information for file: Called the Compa	my to see if the facility was
still active and makin	y synthetic rubber. Online
attiles indicate that to	he Facily may have been
Shift down March Da	OD Searchary took my
name and whome num	bet and Indicated that
sime one usuld noturn	m, call.
	Signed

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY TELEPHONE MEMO TO THE FILE

Please complete with typewriter or black pen.

Later trataco de dasa a lateral	
Date of call: Nov. 15, 200 File no.: RN 101871507 TXD 05742	7,50
· ·	
Phone no.: (432) 332-6834 Subject: Dynagen; Ameripal Symp	01.
Information for file: Spoke unto Lesley Wright From the Ector CAD. She said the plant has been closed six 2002 but it is 87:11 coved by Ameripa Synpl	•
CAD. She said the plant has been closed sin	હ
2002 but it is 8511 wered by Ameripa Syngol	′
Corp, which is also indicated by the property to	1/
infermation.	
	- "
	·
Signed	

